
Advanced BIM & Lean

LCI-UK Summit 29 October 2015












































'Chip' thinking




Pharmaceutical chips


- Air Compression
- Batch Mixing
- Bulk Nitrogen Tank
- Blending
- Crystallisation
- Encapsulation
- Continuous Drying
- Fluid Bed Drying
- Spray Drying
- Continuous Granulation
- High Sheer Granulation
- Roller Compaction
- Sampling
- Sieving
- Product Inspection
- Microfluidic Emulsion
- Wet Bead Milling
- Solution Prep
- Solvent Handling
- Spray Drying
- Tablet Coating
- Tablet Compression
- Wash








Make Pack and Fill







RM Storage

Make

Pack and Fill

Store FP



Ambient Storage



Premix

22 perators

















 $x 20 \text{ years} = 152\text{m}^2$ £2,400/m²


£18,240 (NHS grade D, newly qualified nurse, outside London)


























Truss Services Support Frame Assembly Specification

Generally: Unstrut services assume frame with connection brackets for mounting services inside trusses Related dewlings: CQSTH-QST Structural Support From inside too and borsom choics, max 1200 cts. Nat 8 Bolf Pixings: MRSQ, Pomp, Washer 8 Mylco Nur Installation: The connections that ignorally be pre-installed within the trues, however where falling brisate is, inspaired follow this instructions below:

Assembly Instructions:

1. Unpack COMTR-QST for installation onto the truss.

2. Menally the correct beasion on the truss and by COMTR-QST and the floor need to it.

3. Heariny the correct beasion on the truss and by COMTR-QST and the floor need to it.

3. Heariny bear It and 2 flores each of the mounting brackets, lead the bottle and leave bracket correct leagues on the truss lead cherd.


5. Hearing the leaves tracket profitors and loosty iff bottle it and 2 to each bracket.


6. Side COMTR-QST Whose the location.

7. Traitine bottle 1 and 2 using a leasure whench to lock COMTR-QST into posture.

8. Once all services supports are in place (mar 1200mm cs) installations and place in the stocket.

6. Once all services supports are in place (mar 1200mm cs) installations.







HAZARD DENTIFICATION LEGEND:

HAZARO CIENTIFICATICA Il noro stato horo relever!

To parapris mag

NOTE Present have above use only from construct a transfer of the same.

in not there to be considered a composition boustable of other designers. In unusual or of wedges be officiall to manage of technology.

The stone of quarter road in compression with earlier and remained in the Par Construction in terrogen incommentation.

To right state from the distance of dimensions is bottomized to sky price to the permission over a ray work or the production of why state convenience of any work or the production of any state convenience of the district of the permission of the district of the distric

GSK System Design

Truss to Truss Services Connection IN#043

Dressley Marries

12018-SD-BWL-IN-043

7 20 43



Page Sizo

Truss Services Support Frame - Assembly Specification

Generally: Unistrut services support frame with connection brackets for mounting services inside trusses.

Related drawings: CO#TR-031

Structural Support: From truss top and bottom chords, max 1200 c/s.


Nut & Bolt Fixings: M8x50, Penny Washer & Nyloc Nut


Installation: This component will typically be preinstalled within the truss, however where fitting on site is

required follow the instructions below.


Assembly Instructions:

- 1. Unpack CO#TR-031 for installation onto the truss.
- 2. Identify the correct location on the truss and lay CO#TR-031 on the floor next to it.
- **3.** Remove bolts 1 and 2 from each of the mounting brackets, keep the bolts and lower bracket portions together.
- **4.** Mount CO#TR-031 vertically in approximately the correct location of the truss top chord.
- 5. Reapply the lower bracket portions and loosly fit bolts 1 and 2 to each bracket.
- **6.** Slide CO#TR-031 into its final position.
- 7. Tighten bolts 1 and 2 using a torque wrench to lock CO#TR-031 into position.
- 8. Once all services supports are in place (max 1200mm c/s), install ducts and pipes from above and connect to unistrut horizontal bar using steel straps & fixings. (EXPAND ON THIS)






Oculus









www.myarcsset.net/Manage/FileManager.aspx?asset_number=10000192289






7 In Use


















Comments	
Tell me something	,
Share	

Timeline













Jaimie Johnston Director, Head of Global Systems jjohnston@brydenwood.co.uk